

# Refrigeration Relays, Overloads and Hard Starts

## UPRO SERIES PUSH-ON RELAY

For Refrigeration Systems With or Without Run Capacitors. Maintain a High Efficiency System or Save an Old System.

- Replaces Relay and Overload
- Works on RSIR, CSIR, PSC & CSR Compressors
- Available in Popular Sizes, Ranging from 1/12 hp to 1/2 hp
- “Push-On” Relay Overload
- Quick Connect Push-On Terminals for Run And/Or Start Capacitor
- Wiring Instructions on the Package
- Instructions for Adding a Start Capacitor And/Or Run Capacitor



PART NO.	HP RATING	VOLTS
UPRO21	1/3 to 1/2	115
UPRO41	1/4 to 1/3	115
UPRO81	1/12 to 1/5	115

## URSC SERIES RELAY START CAPACITOR

For Refrigeration Systems With or Without Run Capacitors. Maintain a High Efficiency System or Save an Old System.

- Replaces Current-Type Relays
- Works on RSIR, CSIR, PSC & CSR Compressors
- Provides a Boost for Hard Start and Unbalanced Systems
- No Additional Wires Required

PART NO.	HP RATING	VOLTS
URSC10	1/20 to 1/2	115
URSC20	1/20 to 1/2	220



## RCO SERIES 3 'N 1 RELAY, OVERLOAD AND START CAPACITOR COMBINATION

For Refrigeration Systems Without Run Capacitors.

- Replaces Relay, Overload and Provides a Boost for Hard Start and Unbalanced Systems
- Prevents Low Voltage Starting Problems



PART NO	MOUNTING	START HP RATING	VOLTAGE (VAC)	CONTINUOUS RUNNING AMPS	TRIP IN CURRENT AFTER 6-16 SEC. (AMPS)
RC0210	Quick Connect	1/2	115	13.3	12
RC0410	Quick Connect	1/4 to 1/3	115	6.8	22
RC0810	Quick Connect	1/12 to 1/5	115	4.05	12
RC0220	Quick Connect	1/2	230	7.5	22
RC0420	Quick Connect	1/4 to 1/3	230	4.05	12
RC0620	Quick Connect	1/6 to 1/5	230	1.66	6
RC0820	Quick Connect	1/12 to 1/8	230	1.66	6